

CHIEF MECHANICAL ENGINEER

CHIEF WORKSHOP ENGINEER

LPL

MX

DHD

PRTN

BVP

CWM

CWM/ELECT

CWM/ELECT

CWM

Dy CME

Dy CME (R)
Dy CME (P)
Dy CME (M&P)
Dy. CEE
Dy.CMM

Dy.CME
Dy.CEE

Dy CME
Dy.CPM(EL)
Dy.CMM
Dy.FA&CAO

SPO
WM (R)
WM (C)
DEE
Sr. AFA

PE
DEE
DMO

PM(Mech)
Sr. EE-I
Sr. EE-II

Sr. AFA

WM

AWM (R)
AWM(G)
AIO
ACMT
AEE
AMM
AFA

Principal/ETC
AEE/POH
AEE/PGTC
AWM/R
AWM/M
APO
AMM

AWM (G)
AWM-I
AWM-II
APO, AFA
AEE, APM(SL)
AMMI, AMMII
ACMT

AWM
AMM

AWM
AMM
APO
AFA